



FLYBE DH8D AT BIRMINGHAM ON DEC. 1, 2015, FLAPS PROBLEM

News / Airlines



Photo Copyright © Roland Winkler

PLANESPOTTERS.NET

A Flybe de Havilland Dash 8-400, registration G-PRPB performing flight BE-403 from Belfast City, NI to Birmingham, EN (UK), was on approach to Birmingham's runway 15 when the crew went around reporting problems with **the flaps**. The aircraft entered a hold while the crew was working the checklists. The crew finally prepared the aircraft for a flaps up landing and landed safely on Birmingham's runway 33 at a higher than normal speed (about 170 knots over ground) about 30 minutes after aborting the first approach.

The aircraft is still on the ground in Birmingham about 9 hours after landing.

The airline confirmed the captain took the recommended precautionary actions following a suspected minor technical problem. All passengers disembarked normally.

02 DECEMBER 2015

SOURCE: THE AVIATION HERALD

ARTICLE LINK:

<https://to.50skyshades.com/news/airlines/flybe-dh8d-at-birmingham-on-dec-1-2015-flaps-problem>